



Lead Poisoning Prevention Program

Required Experience for becoming a Lead Paint Risk Assessor

A Maryland Lead Paint Risk Assessor shall have the following experience as per COMAR 26.16.01.16C:

1. Have been an accredited/licensed Lead Paint Inspector Technician for at least 1 year. This information is to be transcribed on your Risk Assessor application in the spaces provided.

If your experience is from another state be sure to enclose a copy of your Inspector Technician or Risk Assessor accreditation certificate or license from that state with your application.

2. Applicant is to list 20 different inspections conducted while appropriately accredited or licensed.

For each inspection list: address, date of inspection and inspection type. Inspections are to be from **separate** residential units, public buildings, or commercial properties unless it is listed with another type of inspection.

Inspection types are either: lead-based paint inspection (paint chip and/or X-Ray Florescent Analyzer (XRF)) or dust inspection (dust wipe/sample).

One of the following shall be satisfied:

- a. List 20 different lead-based inspections
- b. List 5 different lead-based inspections
And
List 15 different dust inspections

Submit this list of your 20 different inspections with your application for Maryland Lead Paint Risk Assessor accreditation.

